









CTSU Equipment Inventory Master List

Equipment/Quantity	Picture	Location
Bladder Scanner – 1	N/A	*Broken – pending replacement July 2020
Ultrasound Machine – 1		Nursing station <i>Near tube station</i>
Zoll Defibrillators – 3		Nursing station <i>On code cart and on wound cart</i>
Philips Monitoring Equipment MX40 Telemetry boxes _____ Aline/Pressure Cables _____ SpO2 Cables _____ Trunk Cables _____ NIBP Cables _____ 5-Lead Grabber _____	<div style="display: flex; flex-wrap: wrap;"> <div style="width: 50%;"> <p>MX40 Telemetry box</p>  </div> <div style="width: 50%;"> <p>SpO2 Cable</p>  </div> <div style="width: 50%;"> <p>Hardwire/Trunk Cable</p>  </div> <div style="width: 50%;"> <p>Pressure Cable</p>  </div> <div style="width: 50%;"> <p>5-Lead Grabbers</p>  </div> <div style="width: 50%;"> <p>NIBP Cable</p>  </div> </div>	Nursing station <i>Telemetry cabinet</i>